

CIVIL AVIATION AUTHORITY OF MALAYSIA

MANDATORY OCCURRENCE REPORT (MOR) - AIRWORTHINESS ASPECT

(Civil Aviation Regulation 2016)

SECTION 1 – SUBMITTER INFORMATION											
1.1	Date of Occurrence		:	19 July 202	3						
1.2	Aircraft Registration	9M-MTE									
1.3	Submitter Type	САМО									
1.4	Organisation Approval / AML N	Num	iber :	CAMO/2016/01							
1.5	Submitter's Designated MOR Reference No. :			MOR/330/23/JUL/03							
SECTION 2 – ADDITIONAL INFORMATION											
2.1	If Submitter Type is CAMO/CA	0	:	Air Operato	Air Operator – Scheduled Operator						
2.2	If Submitter Type is AMO (Part 145/ Part Subpart F)/ AML Holder :			Choose an item.							
2.3	If Submitter Type is POA :			Choose an i	item.						
SECT	ION 3 – MAJOR EQUIPMENT IDI	ENT	ITY								
3.1	.1 AIRCRAFT DETAILS										
(a)	Manufacturer/TC Holder	:	AIRBUS								
(b)	Type/Model	:	AIRBUS A330-300								
(c)	Serial Number	:	1243								
(d)	Total Time Since New TTSN (Hours)	:	49098		(e)	Total Cycles Since New TCSN	:	8132			
3.2	3.2 ENGINE DETAILS										
(a)	Manufacturer/TC Holder	:	PRATT ENGINE								
(b)	Type/Model	:	PW4170								
(c)	Serial Number	:	P735083/P735076								
(d)	TTSN/TTSO (Hours)	:	33370 / 36	911	(e)	TCSN/TCSO	:	6591 / 6037			
3.3	PROPELLER DETAILS										
(a)	Manufacturer/TC Holder	:									
(b)	Type/Model	:									
(c)	Serial Number	:									
(d)	TTSN/TTSO (Hours)	:	/		(e)	TCSN/TCSO	:	/			

SECTION 4 - PROBLEM DESCRIPTION									
	DESCRIPTION OF INCIDENT/OCCURENCE/ETOPS EVENT:								
	9M-MTE return to bay due to ENG #1 stall and failed during Takeoff Roll.								
	DETAILS OF INCIDENT:								
	Low speed aborted Take Off due to ENG #1 stall after selection of Take Off thrust. The Flight Crew had reported ENG #1 Engine Gas Temperature (EGT) over limit followed by tailpipe fire is observed by the other aircraft.								
	CORRECTIVE ACTION :								
	Troubleshooting in progres	ss.							
	MOR PREMILINARY ANALYSIS REPORT TO FOLLOW.								
SECTION 5 – MOR INFORMATION									
5.1	ATA Code		: 71 POWERPLANT						
5.2	Sub ATA Code		:						
5.3	How Discovered		: V – Visual	Specify if other:					
5.4	Nature of Condition		: J – Warning Indication	Specify if other:					
5.5	Precautionary Procedures	onary Procedures : C – Aborted Take Off Specify if other:							
SECTION 6 – SUPPORTING DOCUMENT DETAILS (AMM, AD, SB, CAME, MOE, ETC, DIRECTLY RELEVANT TO OCCURRENCE)									
6.1	Type of Document		: 🗆 Hardcopy 🗆 S	oftcopy					
6.2	Document Name	ocument Name :							
6.3	Document Reference Number :								
SECTIO	ON 7 – SPECIFIC PART OR STI	RUC	TURE CAUSING DIFFICULTY						
7.1	Part Name	:	A330 PRATT ENGINE						
7.2	Part No.	:	PW4170						
7.3	Part Condition	:	ROTABLE						
7.4	Time Since (Hours)	:	33370	Repair	Inspection				
7.5	Manufacturer's Name	:	PRATT ENGINE						
7.6	Serial No.	:	P735083						
7.7	Part Detect Location	:	Zone 500 – Left Wing						
7.8	*If other location (please specify)	:							
7.9	TTSN/TTSO (Hours)	:	33370 /						
7.10	TCSN/TCSO	:	6591 /						
SECTIO	SECTION 8 – COMPONENT ASSEMBLY THAT INCLUDES DEFECTIVE PART								
8.1	Component Name	:							
8.2	Part No.								

CAAM/AW/8503-01 140921

												140921
8.3	Model Number	:										
8.4	Time Since (Hours)	:								Repair	Inspection	
8.5	Manufacturer's Name	:										
8.6	Serial No.	:										
8.7	Location	:										
8.8	TTSN/TTSO (Hours)	:		1								
8.9	TCSN/TCSO	:		1								
8.10	Is the part rotable	:		YES		NO						
SECTION	ON 9 – DECLARATION											
9.1	9.1 V I hereby declare that all the particulars given above are true and correct.											
9.2	Submitter's Name	:	MUH	MUHAMMAD ZULKIFLI BIN SADRI								
9.3	Contact Number	:	03-87	03-87772430								
9.4	Email Address	:	muha	muhammadzulkifli.sadri@malaysiaairlines.com								
CAAM OFFICIAL (MOR Coordinator)												
	Received by :	:							Date	:		
	CAAM Designated MOR Reference : Number	: []	MOR R	Reference	e Nun	nber]						

CAAM Designated MOR Reference Number : [MOR Reference Number]							
CAAM OFFICIAL (Inspector) Assessment (Detail out how assessment is carried out; desktop review, interviews, site inspection, etc. and the conclusion of the assessment).							
Click or tap here to enter text.							
Action (State Inspector's recommended immediate corrective action conveyed to the organisation or state the acceptable immediate corrective action taken by the organisation).							
Click or tap here to enter text.							
Inspector's Signature : Date : Insert date							
Inspector's Name / Stamp :							

INSTRUCTIONS

SECTION 1 – SUBMITTER INFORMATION							
1.5	Submitter must assign its own MOR reference number for the purpose of document control.						
SECTION	SECTION 4 – PROBLEM DESCRIPTION						
	Describe the occurrence in chronological order including any mishaps that occurred or hazard that it presents.						
SECTION	SECTION 5 – MOR INFORMATION						
5.2	5.2 Refer to the Sub ATA Code listed in CAGM 8503.						
SECTION	ON 6 - SUPPORTING DOCUMENT DETAILS						
6.2	6.2 Related document that helps illustrates the occurrence.						
SECTION	ON 7 - SPECIFIC PART OR STRUCTURE CAUSING DIFFICULTY						
7.1	7.1 Specific part or structure being the cause or contribute to the cause of the occurrence.						
	*Note: if the detail information was not able to be acquired within 48 hours of the occurrences for the						
	compilation of the report, the detail shall be included in the pre-analysis report of the occurrence.						
SECTION	ON 8 - COMPONENT ASSEMBLY THAT INCLUDES DEFECTIVE PART						
8.1	.1 The component assembly that contains a defective part that cause the occurrence.						
	*Note: if the detail information was not able to be acquired within 48 hours of the occurrences for the						
	compilation of the report, the detail shall be included in the pre-analysis report of the occurrence.						