Sequence No. W/O malaysia 3 5232266 9M-MSE B73NG B738 B738C1 Copy ATA osition Туре P N/A N/A 200 05-50 N/A UNSCHEDULED MAINTENANCE PIREP CHECKS Upper Half of the Fuselage Туре Reference Description MH2640 Flight Description Step 1 DON LIM TSUNG (2109691), 16.Jul.2023 **BIRD STRIKE** DURING T/O R/WY 32R AT ABOUT 400', BIRD STRIKE AT LOCATION WINDSHIELD WINDOW L1. DON LIM TSUNG (2109691), 16.Jul.2023 VIS INSP UPON L1 WINDSHIELD FOUND NO SIGN OF BIRD STRIKE, NOSE RADOME AREA INSP, SATIS, PITOT PROBE, TAT AND AOA SENSOR THOROUGH INSP, FOUND NO DAMAGE. BMM 05-51-18 REV 81. DON LIM TSUNG (2109691) Work Performed Workorder Closed otal Aircraft Hours **BKI** 16.Jul.2023 11:30 22423:43 15054 DON LIM TSUNG (2109691) *Certificate of Release To Service Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia 16.Jul.2023 11:30 requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service AMO/2023/01 DON LIM TSUNG (2109691) Commercial Information Customer: Project Number: LINE 738