

## INFRINGEMENT REPORT FORM

ANS/SAF/ANSPM/ 04/09

Note. 1 - To be completed by controllers reporting an infringement of MCAR 2018 and Rules of the Air and Air Traffic Control by pilots of aircraft operating in the Kuala Lumpur / Kota Kinabalu Flight Information Region.

Note. 2 - \* Delete as appropriate Aircraft identification and type AXM6307 (9MAGQ)/ A320 A) Operator AIR ASIA B) Captain's Name \_\_\_\_UNKNOWN\_\_\_\_\_ C) Date and time of incident (UTC) \_\_\_\_0348\_\_\_\_ D) Aerodrome of Departure \_\_\_\_\_WMKL\_\_\_\_\_ E) Aerodrome of Destination \_\_\_\_\_WMKK\_\_\_\_\_ F) \* Altitude / Flight Level Descending \* Climbing / Descending / G) Level IFR / VFR IFR H) IMC / VMC (as reported by pilot) 1) Estimated position at time of incident \_\_\_\_3nm touchdown\_\_\_\_\_ J) Name of ATCO raising report Abdul Sakiff Bin Harun\_\_\_\_\_ K) Details of infringement & consequence L) The pilot failed to read back the landing clearance correctly as required in CAD 11 and create unnecessary transmission by ATC to repeat the clearance. Landing clearance was given twice and the pilot only read back his callsign for both landing clearances. This is practiced by a lot of other pilots however the clearance is mostly corrected after being transmitted twice. Rule or Regulation contravened by pilot CAD 11\_\_\_\_\_ M) Whether pilot or Operator advised of incident (Tick) N) Yes ✓ No Signature: ...... Date: ...31/7/2023..... Name: Abdul Sakiff Bin Harun..... Time: ...0629UTC..... Remarks by Watch Supervisor/Manager Noted. Raport will despet to ment Signature: for further action O)

Name:

	Date:	
P)	Remarks by Investigation Officer	
	Signature:	
	Name:	
	Date:	
Q)	Recommendation / Action taken:	
	Signature:	CERRET
	Name:	
	Date:	
R)	Copy sent to operator	Date:
	Feedback to reportee	Date:

