W/O Registration malaysia 2 5230204 9M-MLR B73NG B738 B738C2 Copy Туре Position Ρ N/A 05-50 N/A 100 N/A UNSCHEDULED MAINTENANCE PIREP CHECKS Lower Half of the Fuselage Reference Description Туре **Flight** MH109 / 54365 Description Step 1 SARMAN BIN MASROM (2109772), 09.Jul.2023 BIRD STRIKE AT FWD LOWER FUSELAGE JUST PRIOR TO TOUCHDOWN Action Step 1-1 SARMAN BIN MASROM (2109772), 09.Jul.2023 BIRDSTRIKE INSPECTION CARRIED OUT AS PER AMM 05-51-18 REV 81 FOUND NIL BIRDSTRIKE IMPACT ON SAID AREA.AREA INSPECTED FOR DAMAGE FOUND NIL ABNORMALITIES. OTHER AREAS INSPECTED FOUND SATISFACTORY. SARMAN BIN MASROM (2109772) Work Performed Workorder Closed otal Aircraft Cycles osing *Sign / Stamp **KUL** 09.Jul.2023 01:20 30176:14 15802 SARMAN BIN MASROM (2109772) *Certificate of Release To Service Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia 09.Jul.2023 01:20 requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service AMO/2023/01 SARMAN BIN MASROM (2109772) Commercial Information

Customer:

Project Number: LINE 738