

## **CIVIL AVIATION AUTHORITY OF MALAYSIA**

## **OCCURRENCE REPORT FORM**

Date received: (ATM Division use only)	Media In	npounded	Yes		No	✓	IO: (ATM Division u	se only)		
Occurrence: Loss of Separation / AIRPROX TCAS RA Alert Level Bust		Date: 28 Jun 2023				Case No: (ATM Division use only)				
		Time (UTC): 0248				Workload:				
Ground Incident		Sector /	Position /			▎┝	Normal			
✓ Go Around - Inadequate	e Space	Frequency:				✓ High				
	•	ADC2 / 118.5 MHz								
	Lo	cation of	the Inci	den	t					
On Ground					n Air					
Runway: 32L		Fix	Rout	Route		ince				
Taxiway:						Horizontal	Vertical			
Intersection:										
AIRCRAFT INVOLVED:		Λ i.	oroft 1				Aircraft 2			
Call Ciam		Aircraft 1								
Call Sign		ETD418				MMA501				
Identification (SSR Code)										
Aircraft Type		B777				A319				
		☐ Air Carrier ☐ Military				☐ Air Carrier ☐ Military				
		☐ Gener	al Aviatio	n		☐ General Aviation				
		☐ Other				☐ Other				
Departure	OMAA				VYYY					
Destination		WMKK				WMKK				
Actual (FL / Altitude)										
Cleared (FL / Altitude)										
Flight Phase		☑IFR □VFR				☑IFR □VFR				
G	☐ Climbing				☐ Climbing					
			Descending				☐ Descending			
	 □ Cruise				☐ Cruise					
	☐ Holding Pattern				☐ Holding Pattern					
	☐ Approach				 ☑ Approach					
Was the aircraft in radar coverage?		☐ Yes ☐ No				☐ Yes ☐ No				
Communication with the pilot		□Yes □No				☐ Yes ☐ No				
Did either pilot report the occurrence?		□ Yes □ No				□Yes □ No				
Occurrence related to ACAS / TCAS		☐ TA ☐ RA ☐ Not Sure				☐ TA ☐ RA ☐Not Sure				
ACAS / TCAS Equipped	. 0, 10		 ] No □!			_	es □No □N			
*Did either pilot ask for traffic		☐ Yes [		101 0	Juio	_	es 🗆 No	vot ourc		
information?		□ 103 L	_ INO			ш.	C3 110			
*If 'Yes', was it before manoe	uvring?	□Yes I	□ No			ΠY	es 🛮 No			
Observed pilot response:		☐ Descent ☐ Climb				□ Descent □ Climb				
		□ Turn	☐ No F	Respo	nse	ПΤ	urn 🛮 No F	Response		
Was the action taken by the p	oilot	☐ Yes	□No			ΠY	es □ No			
justified in your view?						_				
Did the occurrence disrupt your activities		☐ Yes ☐ No				□ Yes □ No				
Will recorded data become av	vailable	☐ Yes	□No			ΠY	es 🗆 No			

Description of the occ	urrence:								
ETD418 go around ru	unway 32L due to lack	of sp	pacing with	prec	eding MI	MA50	1.		
Name of the Reportee	oortee <u>:</u> Siwa a/l Mathaban					Signature:			
Designation:	PKTU		Date:13 Jul 2023						
Suggest ATCO to be	relieved from operati	ional	duties: Y	es"	N	√o			
ATCO Involved:			Traine	e Inv	olved:				
Material Attached:	Controller's Report		Logbook		FPL		Flight Strips		
	Break Shift Roster		NOTAM		META	7			
Name:	Signature:								
Designation:					С	)ate:			

Forwarded to Safety Management Unit, ATM Division on ...13 Jul 2023... for investigation.

Note: Please tick  $\checkmark$  where appropriate