
		Sequence No.		W/O <b>5233278</b> Copy		Barcode  WO5233278		Registration <b>9M-MXV</b> B73NG B738 B738C1	
Type <b>P</b> PIREP	Origin <b>N/A</b>	ATA <b>05-50</b> UNSCHEDULED MAINTENANCE CHECKS		Position <b>N/A</b>		Zone <b>100</b> Lower Half of the Fuselage		Area <b>N/A</b>	
Type		Reference				Description			
<b>Flight</b>		<b>MH2637</b>							
Description Step 1 MUHAMMAD SYAHMIE BIN RAMLI (2354319), 03.Sep.2023									
BIRD STRIKE DURING TAKE OFF									
Action Step 1-1 MUHAMMAD SYAHMIE BIN RAMLI (2354319), 04.Sep.2023									
BIRD STRIKE CONDITIONAL INSPECTION C/OUT AS PER AMM 05-51-18 REV 81 DATED JUN 15/23. BLOOD STAIN AT LH SIDE OF FUSELAGE CLEANED. FURTHER INSPECTION NIL ABNORMALITIES. SATISFACTORY.									
								Performed Signatory MUHAMMAD SYAHMIE BIN RAMLI (2354319)	
Work Performed Workorder Closed									
Date <b>04.Sep.2023 01:00</b>		Total Aircraft Hours <b>23842:20</b>		Total Aircraft Cycles <b>12196</b>		Place / Station <b>KUL</b>		Closing *Sign / Stamp MUHAMMAD SYAHMIE BIN RAMLI (2354319)	
*Certificate of Release To Service								Date <b>04.Sep.2023 01:00</b>	
Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service								*Sign & Stamp MUHAMMAD SYAHMIE BIN RAMLI (2354319)	
AMO/2023/01									
Commercial Information									
Customer:									
Project Number: LINE_738									