

		Sequence No.	W/O	Barcode	Registration
			5226394		9M-MTX
			Copy	WO5226394	A330 A332 A332P
Type	Origin	ATA	Position	Zone	Area
P	N/A	05-50	N/A	200	N/A
PIREP		UNSCHEDULED MAINTENANCE CHECKS		UPPER HALF FUSELAGE	
Type	Reference		Description		
Flight	MH2645				
Description Step 1					
SUNG TIN CHENG (2109153), 28.Jun.2023					
BIRD STRIKE					
BIRDSRIKE DURING LANDING ROLL					
Action Step 1-1					
SUNG TIN CHENG (2109153), 28.Jun.2023					
BIRD STRIKE CONDITIONAL INSPECTION C/OUT AS PER AMM 5-51-14 REV 100 FOUND BIRD STAIN ON F/O FWD WINDSHIELD. BIRD STAIN CLEANED AS REQUIRED USING WATER FOUND SATISFACTORY. SAID AREA AND SURROUNDING AREA RE-INSPECTED AS PER AMM 5-51-14 REV 100 FOUND NIL ABNORMALITIES OBSERVED. SATISFACTORY.					
					Performed Signatory
					SUNG TIN CHENG (2109153)
Work Performed Workorder Closed					
Date	Total Aircraft Hours		Total Aircraft Cycles	Place / Station	Closing *Sign / Stamp
28.Jun.2023 13:09	57706:30		8301	KUL	SUNG TIN CHENG (2109153)
*Certificate of Release To Service					
Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service					Date
					28.Jun.2023 13:09
AMO/2023/01					*Sign & Stamp
					SUNG TIN CHENG (2109153)
Commercial Information					
Customer:					
Project Number: LINE_330					