		Sequence No.	W/O	E	Barcode	Registration
mala	YSIA		5227725			9M-MLO
			Сору		WO5227725	B73NG B738 B738C2
Туре	Origin	АТА	Position	ľ	Zone	Area
Р	N/A	05-50	N/A		ALL	N/A
PIREP		UNSCHEDULED MAINTENANCE CHECKS			ALL ZONES	
Туре	Reference Description					
Flight	MH2517					
Description Step 1 Nur HaFiZUDDIN BIN AB HALIM (2109046), 11.Jul.2023						
BIRD STRIKE AFTER TOUCH DOWN RUNWAY 14L KUL						
Action Step 1-1 NUR HAFIZUDDIN BIN AB HALIM (2109046), 11. Jul. 2023						
BIRD STRIKE INSPECTION C/OUT AS PER AMM 05-51-18 REV 81 DATED JUNE 15/2023. NIL SIGN OF IMPACT OR DAMAGE FOUND. NIL BLOOD						
STAIN FOUND. INSPECTION C/OUT FROM RADOME TO AFT SECTION OF FUSELAGE, NIL FINDING. ENGINE BOTH SIDE IINSPECTED FOR						
INGESTION ALSO NIL FINDING AS PER AMM 71-00-00. SATISFACTORY.						
						Performed Signatory
						NUR HAFIZUDDIN BIN AB HALIM
(2109046)						
Work Performed Workorder Closed Date Total Aircraft Hours Total Aircraft Cycles Place / Station Closing *Sign / Stamp						
11.Jul.20	023 11:05	30284:55	16141		KUL	NUR HAFIZUDDIN BIN AB HALIM (2109046)
*Certificate of Release To Service						
Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service 11.Jul.2023 11:05						
AMO/2023/01						*Sign & Stamp NUR HAFIZUDDIN BIN AB HALIM (2109046)
Commercial Information						
Customer:						
Project Number: LINE_738						
-						