CAAM	D / OTHER WIL	DLIFE STRIE	(E REPORTIN	G FORM	
1. Name of Operator / Aircraft Callsign	2. Aircraft Make/Model		3. Engine Make/Model		
MALAYSIA AIKLINGS BERHAD /	0727 800		C=10.56. 7		
MH 2517	B737-800		CFM56-7		
4. Aircraft Registration	5. Date of Incident		6. Local Time of Incident		
gmm <i>Lo</i>	11 , 0	07 , 2023	□ Dawn □ Dusk <u>18</u> H		
-1		onth Year	☑ Day ☐ Night ☐ AM ☑ PM		
7. Airport Name	8. Runway Used		9. Location if En Route	(Nearest Town/Reference &	
			State)	,	
KUL	14 L				
10. Height (AGL)	11. Speed (IAS)		_		
	80 KT	C			
O	80 FI.	?			
12. Phase of Flight	13. Part(s) of Aircraft S	truck or Damaged	1		
☐ A. Parked					
☐ B. Taxi		Struck / Damaged		Struck / Damaged	
☐ C. Take-off Run	A. Radome	Z -	H. Propeller		
☐ D. Climb	B. Windshield		I. Wing/Rotor		
☐ E. En Route	C. Nose		J. Fuselage		
☐ F. Descent	D. Engine No. 1		K. Landing Gear		
☐ G. Approach	E. Engine No. 2		L. Tail		
☑ H. Landing Roll	F. Engine No. 3		M. Lights		
Z 11. Landing Non	G. Engine No. 4		N. Other: (Specify)		
14. Effect on Flight	15. Sky Condition		16. Precipitation		
None	☐ No Cloud		☐ Fog		
☐ Aborted Take-Off	Some Cloud		☐ Rain		
☐ Precautionary Landing	☐ Overcast		☐ Snow		
☐ Engines Shut Down	- Ovcidast		□ Chow □ None		
☐ Other: (Specify)			None		
17. Bird/Other Wildlife Species	10 Number of birds as	on and/or atruck	19. Size of Bird(s)		
17. Bird/Other Wildlife Species	18. Number of birds seen and/or struck		19. Size of Bird(s)		
	Number of Birds	Seen / Struck	Small		
	1	ø ø	Medium		
	2-10		□ Large		
	11-100				
	More than 100				
20. Pilot Warned of Birds					
21. Remarks (Describe damage, injuries and	other pertinent information)				
Reported by (Optional)	Title :		*send all bird remains	including feather	
			fragments to:		
	Date:				

THIS INFORMATION IS REQUIRED FOR AVIATION SAFETY



SUPPLEMENTARY BIRD/WILDLIFE STRIKE REPORTING FORM OPERATOR COSTS AND ENGINE DAMAGE INFORMATION

A. BASIC DATA										
Aircraft Make/Model :873 +860	Aircraft Make/Model : 18737 800									
B. COST INFORMATION										
Aircraft time out of service										
C. SPECIAL INFORMATION ON ENGINE DAMAGE STRIKE										
Engine position number		1	2	3	4					
	ined failure									
a la contra la coma	fire									
snutdown shutdown – t	vibrationemperature									
	fire warning									
shutdown - oth	er (specify)									
	- unknown									
Estimated percentage of thrust los Estimated number of birds ingeste		_	_		_					
· ·					_					
Bird/Wildlife species										
* These may be difficult to determine but even estimates are useful.										
Send all bird remains feather fragments to:										
Reported by:	Title :									
	Date:									