
		Sequence No.	W/O	Barcode	Registration
			5223162		9M-MLS
			Copy	WO5223162	B73NG B738 B738C2
Type	Origin	ATA	Position	Zone	Area
P	N/A	05-00	N/A	ALL	N/A
PIREP		SCHEDULED/UNSCHEDULED MAINTENANCE		ALL ZONES	
Description Step 1					
SIAEC SINGAPORE (SIAEC) (SIN.ENG), 30.Jun.2023					
FOR INFO FOUND 2 DEAD BIRD ON NOSE GEAR					
FOR INFO FOUND 2 DEAD BIRD ON NOSE GEAR STRUCTURE ENGINEER REMOVE BIRD INSPECTION C/OUT. NIL DAMAGE					
Action Step 1-1					
SIAEC SINGAPORE (SIAEC) (SIN.ENG), 30.Jun.2023					
FOR INFO FOUND 2 DEAD BIRD ON NOSE GEAR					
NLG INSPECTED NIL DAMAGE OR ABNORMALITIES					
					Performed Signatory
					SIAEC SINGAPORE (SIAEC) (SIN.ENG)
Work Performed Workorder Closed					
Date	Total Aircraft Hours	Total Aircraft Cycles	Place / Station	Closing *Sign / Stamp	
30.Jun.2023 07:39	25408:45	14057	SIN	SIAEC SINGAPORE (SIAEC) (SIN.ENG)	
*Certificate of Release To Service					
Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service					Date
					30.Jun.2023 07:39
					*Sign & Stamp
FAMO/2017/39					SIAEC SINGAPORE (SIAEC) (SIN.ENG)
Commercial Information					
Customer:					
Project Number: LINE_738					