
		Sequence No.	W/O	Barcode	Registration
			5230066		9M-MXH
			Copy	WO5230066	B73NG B738 B738C1
Type	Origin	ATA	Position	Zone	Area
P	N/A	05	N/A	ALL	N/A
PIREP		SCHEDULED/UNSCHEDULED MAINTENANCE		ALL ZONES	
Description Step 1					
SUSPECTED BIRD STRIKE AT RADOME AREA					
Action Step 1-1					
RADOME AREA , FORWARD FUSELAGE AND ENGINE INSPECTED AS PER AMM 05-50-18 REV 81 JUNE 15/2023.NIL ABNORMALITIES. FOUND SATIS.					
					Performed Signatory
					SH KHALID BIN SHAIKH SAAID (2105327)
Work Performed Workorder Closed					
Date	Total Aircraft Hours	Total Aircraft Cycles	Place / Station	Closing *Sign / Stamp	
12.Jul.2023 03:43	32879:01	16081	KUL	SH KHALID BIN SHAIKH SAAID (2105327)	
*Certificate of Release To Service					
Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service					Date
					12.Jul.2023 03:43
AMO/2023/01					*Sign & Stamp
					SH KHALID BIN SHAIKH SAAID (2105327)
Commercial Information					
Customer:20002118					
Project Number: LINE_738					